


# HARDNESS SCALES (INCREASING HARDNESS)



NOTE: THE DUROMETER "A" SCALE IS USED FOR THE SOFTER URETHANES. THE DUROMETER "D" SCALE IS USED FOR THE HARDER COMPOUNDS (ABOVE 95A DUROMETER).